



Hedquarters and Offices- Production Plant

Via Marconi 4/6, 10060 ROLETTO (TO) ITALIA Tel.:+39 0121 342256/342248/342716 Fax:+39 0121 342244

REV. 2 del 10/08/2015







Hedquarters and Offices- Production Plant Via Marconi 4/6, 10060 ROLETTO (TO) ITALIA

Via Marconi 4/6, 10060 ROLETTO (TO) ITAL Tel.:+39 0121 342256/342248/342716 Fax:+39 0121 342244





13. Screw the lower discharge plug back to the place and fill, using water coming out the leakage or pouring water from the outside, the Duofit cavity reducing the presence of air at the minimum possible and finally close the top plug.



"MULTISIZE" - "LARGESIZE" COUPLINGS DO NOT PREVENT PIPE AXIAL MOVEMENT



Hedquarters and Offices- Production Plant

Via Marconi 4/6, 10060 ROLETTO (TO) ITALIA Tel.:+39 0121 342256/342248/342716 Fax:+39 0121 342244